Friday, June 10, 2011 11:44:52 AM

Item ID:

D3463-041

Revision ID:

Item Name:

Step Weldment Assembly

Start Date:

6/10/2011

Start Qty: 4.00

Required Date: 6/15/2011

Req'd Qty: 4.00

Accept



Setup Start

Stop



Cust Item 1D:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Date: // 0/10

Date:

0.00

Tooling:

SPC (Y/N):

Date: Date:

Start Run

Stop



Sequence ID/ Work Center ID Operation Description Set Up/ Run Hours

Tool ID

Tool# Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

Draw Nbr

Revision Nbr

D3463

Rev B

100

Large Fab

0.00

Large Fab Large Fab

Weld assembly as per dwg D3463 using DT8875

EZ 11-7-6

110

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

Memo

Memo

0.00

Memo

0.00

Ga 11. 07.08

OC5- Inspect part completeness to step on W/O

30/ Foly 3000

120

Quality Control

Work Order ID 70532

Friday, June 10, 2011 11:44:52 AM

Item ID:

D3463-041

Revision ID:

Item Name:

Step Weldment Assembly

Start Date:

6/10/2011

Start Qty: 4.00

Required Date: 6/15/2011

Reg'd Qty: 4.00



Accept



Setup Start



Stop

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date: Date:

Stop

Start



OC:

Date:

SPC (Y/N):

Set Up/

Tool ID

Tool# Plan

Code

Accept Qty

Run

Reject Reject Number Qty

Insp. Stamp

Sequence ID/ Work Center ID

Operation Description

White Gloss(Ref.4.3.5.2) per QSI005 4.3-Steel

Run Hours

0.00

2 \$ Bl 11-7-7.

Powdercoat

Powder Coating

1- Mask areas indicated on dwg D546

140

Wing Walk as per dwg QS1005 4.4 Batch //7263-0.00

HandFinish

Memo

Hand Finishing

0.00

150

OC3- Inspect Part Finish

0.00

Memo

0.00

Quality Control

2 d M 1/7/11

Work Order ID 70532

Friday, June 10, 2011 11:44:52 AM

Item ID:

D3463-041

Revision ID: Item Name:

Step Weldment Assembly

Start Date:

6/10/2011

Start Qty: 4.00

Required Date: 6/15/2011

Req'd Qty: 4.00



Reference:

Approvals:

OC:

Process Plan:

Date:

Date:

Tooling:

SPC (Y/N):

0.00

0.00

Set Up/

Run Hours

Identify as per dwg & Stock Location

Sequence ID/

Work Center ID

Packaging

Packaging

170

160

Operation

Description

Memo

OC21- Final Inspection - Work Order Release

Memo

Quality Control

Accept

Setup Start



Cust Item ID:

Customer:

Tool ID

Date:

Date:

Tool# Plan Accept Qty Code

Reject Oty

Run

Reject

Start

Stop

Insp. Number

Stamp

MF 11-07-12

0.00

0.00

Picklist Print

Friday, June 10, 2011 11:44:58 AM

Work Order ID: 70532

D3463-041 Parent Item:

Parent Item Name: Step Weldment Assembly



Start Date: 6/10/2011

Start Qty: 4.00

Required Date: 6/15/2011

Required Qty: 4.00

1925				
C	om	m	en	ts:

Manufactured

Manufactured

Manufactured

No

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
238-806 SS DOWEL PIN 1" LONG		Purchased	No			100	Each	92.0000	2 .	8 [Z	11-7	7-4.	
33 DOWEL FIN 1 CONG				Location		Loc	Qty	Loe Code					
				ST	T17606		92 92		-	8	-		
D3453-3		Manufactured	No	Comment	-	100	Each	0.0000		4			

Clevis
D3453-5

1/3403-0		

Plug		

D3463-1
Am
D3463-3

ATTITLE OF THE PERSON OF THE P	
D3463-3	
Step	

	100	Each	15.0000		EZ 11-7-4
Location	1	oc Qty	Loc Code		
WA023		15			-4
59204	100	15 Each	0.0000	1	4
67948X4					EL 11-7-4
	100-	Each	26.0000		2 117-6

Location	Loc Qty	Loc Code	
WA025	26		1
46269	26		

Friday, June 10, 2011 11:44:58 AM

Work Order ID: 70532

Parent Item:

D3463-041

Parent Item Name: Step Weldment Assembly



Start Date: 6/10/2011

Required Date: 6/15/2011

Start Qty: 4.00

Required Qty: 4.00

D3463-5

End Cap

D3463-7

Drag Arm

Manufactured

Manufactured

Each

100

13.0000

Q 11-7-6

Location WA004

Loc Qty 13 13 100 Each Loc Code

3.0000

EL 127-6

Location

WA025


Loc Qty

Loc Code



DESIGN RF	DRAWN BY RF	DAKLAEKUSTA		
CHECK	APPROVED H	DRAWING NO. D3463	REV. B SHEET 1 OF 4	
DATE		TITLE	SCALE	
	05.12.05	STEP WELDMENT	18	
Α	05.09.20	NEW ISSUE		
В	05.12.05	REVISE DIM.; D3463-5 WAS D3	463-5F	

0.06



NOTES:

D3463-041 OPPOSITE

- 1) WELD PER DART QSI 004
 2) FINISH: POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3
 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 4) ALL DIMENSIONS ARE IN INCRES

D3463-042 STEP WELDMENT ASSEMBLY


- 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010
- 6) IDENTIFY WITH DART P/N USING FINE POINT PERMANENT INK MARKER

COPYRIGHT @ 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN RF	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO	
CHECKED	APPROVED	DRAWING NO.	REV. B SHEET 2 OF 4
DATE 05.	12.05	STEP WELDMENT	SCALE 1:4



NOTES:


- 1) MATERIAL: AISI 316/304 SS SEAMLESS TUBING (REF. DART SPEC. M304TR1.000W.120)
 2) FINISH: NONE
 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 4) ALL DIMENSIONS ARE IN INCHES
 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.025

COPYRIGHT © 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN RF	DRAWN BY RF	DART AEROSPAC HAWKESBURY, ONTARIO	
CHECKED	APPROVED #	D3463	REV. B SHEET 3 OF 4
05.12.05		STEP WELDMENT	SCALE 1.4



D3463-7 DRAG ARM


NOTES:

- 1) MATERIAL: AISI 316/304 SS SEAMLESS TUBING (REF. DART SPEC. M304TR0.750W.120)
- 2) FINISH: NONE
 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 4) ALL DIMENSIONS ARE IN INCHES
 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010

COPYRIGHT @ 2005 BY DART AEROSPACE LTD.



DESIGN RF	DRAWN BY RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
CHECKED	APPROVED	DRAWING NO.	REV. B	
05.12.05		STEP WELDMENT	SCALE	



NOTES:

- 1) MATERIAL: AISI 304/316 SS SHEET, 0.060 THICK (REF. DART SPEC. M304S16GA)
- 2) FINISH: NONE
 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 4) ALL DIMENSIONS ARE IN INCHES
 5) BREAK ALL UNMARKED SHARP EDGES 0.005 TO 0.010

COPYRIGHT © 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.